

Procedure Card for IDT2300

HEROIN BLACK TAR IDENTIFICATION

Substance Test

Read Before Use

As a precaution, gloves and eye protection should be worn when handling drug substances and using test units. Do not prove probe once a capsule is broken. In the unlikely event of a splil, rinse affected area thoroughly with water. Keep out of reach of children. All results are presumptive. If necessary, further testing by a competent drug testing lab can provide additional identifications.

Remove the Smart-TipTM probe from test unit.

Sample suspected substance.

Powder

Touch Smart-TipTM probe to

sample.



Tablet/Brick

Firmly press Smart-TipTM probe on the tablet while scrubbing in a circular motion until the tip is completely covered with substance.



Test Preparation



Do not continue unless probe is locked below the Flex Pins nd cannot e removed from the



Gently shake test unit for 2-3 seconds.



Results



H

The appearance of a purple color indicates the presence of an opiate such as Heroin, Morphine or Codeine.




If no purple color develops, an opiate, such as Heroin, Morphine or Codeine, is not present.



Proceed to Dilution (steps 6-9), regardless of whether or not a color appeared.








Gently shake test unit for 2-3 seconds.



Wait 5 minutes. The test window will warm up. This is normal.

Dilution





Gently shake test unit for 2-3 seconds.



The test window will warm up. This is normal.



Disposal

After Dilution, the test kit is safe to dispose of in the trash.

